		AND HUMAN SERVICES  & MEDICAID SERVICES	15-15	- (	11111111	FOR	D: 03/03/2016 MAPPROVEE D: 0938-0391
STATEMEN AND PLAN	T OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1		CONSTRUCTION - MAIN BUILDING 01		TE SURVEY MPLETED
		445360	B. WING_			02	/29/2016
NAME OF	PROVIDER OR SUPPLIER				EET ADDRESS, CITY, STATE, ZIP CODE		
TENNO\	/A HEALTH CARE-TEN	NOVA TCU			EAST OAK HILL AVENUE OXVILLE, TN 37917		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	FEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL CC IDENTIFYING INFORMATION)	IÐ PREFIX TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	) BE	(X5) COMPLETION DATE
K 130 SS=D	NFPA 101 MISCELL OTHER LSC DEFIC	ANEOUS HENCY NOT ON 2786	K 13	30 1	The TCU Administrator determing no residents were adversely affer this deficiency.		During the survey
	Based on observation facility failed to main barriers and commu (NFPA 101 2000 Edi 19.1.1.1.2, 19.1.1.4.4	tion Section 8.3.5.1, 1, 19.1.1.4.2)		3)	<ul> <li>All residents had the potential to affected by this deficiency; there the TCU Administrator oversaw implementation of the following corrective actions.</li> <li>Corrective actions put into place ensure the deficient practice doe recur include the following:</li> </ul>	fore,	Dates as noted below
K 147 SS≂E	director on 2/29/16 a unsealed penetration the fire rated ceiling is 327.  This finding was verif Supervisor and acknowledge Administrator during 2/29/16.  NFPA 101 LIFE SAFI Electrical wiring and with NFPA 70, Nation This STANDARD is a Based on observation failed to maintain electrical to maintai	erview with the maintenance t 12:40 PM revealed an a around a plumbing pipe in in the cross corridor by room	K 147		a) The ceiling penetration of sealed on 03/01/2016. b) Requirements for maintainthe fire resistance of fire barriers and communicate openings were reviewed applicable Engineering stock the Plant Manager. c) The policy entitled "Build Maintenance Program" of reviewed and determine inadequate. The facility of adopt a new policy entitle "Rated Wall, Floor and Communication of the fire resistance of fire barriers and communicate openings by 03/31/16 by Plant Manager via reviewed this new policy.	sining ting with aff by ling vas d to be vill ed eiling ll aff will ning the	03/01/16 03/01/16 03/31/16

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: LIJ121

Facility ID: TN4714

If continuation sheet Page 1 of 2

Summary Statement of Deficiencies	Tag		Plan of Correction	Completion Date
	K130		The policy "Rated Wall, Floor and Ceiling Assembly Inspections" will be covered during Engineering Department new associate training. A member of the Engineering	04/01/16 and ongoing
			Department participates in the hospital-wide Daily Safety Huddles so that any issues which impact patient safety are able to be quickly escalated to the hospital leadership team for resolution.	Current and ongoing
	:	4) Corrective follows:	e actions will be monitored as	
		· (	Inspections will be performed to determine compliance with maintaining the fire resistance of fire barriers and communicating openings per policy.	Inspections to start 04/01/15
		ь) і с с f	Inspections will be done on a monthly basis, and will continue until substantial compliance has been achieved for 3 consecutive months.  Inspections will then be done on a quarterly basis thereafter.	Inspections to start 04/01/15
		c) I t a a	nspections are performed by the Plant Manager or designee, and any noted deficiencies are addressed by the Plant Manager with applicable Engineering staff immediately.	Inspections to start 04/01/15
		d) A a r a T	Results of inspections and actions taken in response to esuits are aggregated, and trended at the ransitional Care Unit quality neetings.	Add to TCU quality meeting agenda by 03/31/16; to start
		e) C t c n fi T u	Overall results are reported to he hospital-wide Environment of Care Committee and Quality/Safety Committee on a nonthly basis, and will be orwarded to the Board of Trustees every other month until the inspections are completed.	with next meeting.  Add to EOC, QSC, and Board of Trustees meeting agendas by 03/31/16;
Pagi	e 2 of 5			to start with next meetings.

revised policy.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/03/2016 FORM APPROVED OMB NO. 0938-0391

	T OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			E CONSTRUCTION 01 - MAIN BUILDING 01		E SURVEY PLETED
		445360	B. WING	<del></del>		02/	29/2016
NAME OF PROVIDER OR SUPPLIER TENNOVA HEALTH CARE-TENNOVA TCU			90	TREET ADDRESS, CITY, STATE, ZIP CODE 00 EAST OAK HILL AVENUE NOXVILLE, TN 37917		*	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI) TAG	ĸ	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BĘ	(X5) COMPLETION DATE
K 147	director on 2/29/16 revealed the followin  1. The ground faul room falled to functi 2. Wheelchairs sto panels, not providing 3. Outlet loose in a stairwell. 4. Outlet loose in a These findings were	between 12:05 and 1:00 PM ng;  It receptacle in the soiled linen on properly, ored in front of electrical g clear space, corridor in front of exit corridor by room 333.  It verified by the maintenance dedged by the administrator erence on 2/29/16.		47	1) The TCU Administrator determine no residents were adversely affect these deficiencies.  2) All residents had the potential to affected by the deficiencies; there the TCU Administrator oversaw implementation of the following corrective actions.  3) Corrective actions put into place the ensure the deficient practice does recur include the following:  a. The ground fault circuinterrupter was reparative on 03/03/16.  b. The wheelchairs were removed from in from the electrical panels, new lock was placed the electrical room, of 3/1/16 — which restrive access to the electrical room to Engineering personnel only.  c. The loose outlets were tightened on 3/1/16.  d. Requirements for maintaining electrical wiring and equipment were reviewed with applicable Engineering staff by the Plant Market Policy entitled "Patient Room Electrical PMs" was reviewed a determined to be inadequate. The policy entitled "Patient Room Electrical PMs" and were revised accordingly, applicable Engineering staff will be re-educal engineering staff will engineering staff will engineering staff will engineering staff will engineering engineering staff will engineering engineering engineering engi	ed by  e fore,  not  uit ired  e nt of and a on on on ots al  re  I t og nager.  ical end  cy will be and all	Dates as noted below.  03/03/16  03/01/16  03/01/16
					on requirements for maintaining electrica wiring and equipmen 03/31/16 by the Plan Manager via review o	it by it	

Summary Statement of Deficiencies	Tag	Plan of Correction	Completion Date
	K147	f. The policy entitled "Patient Area Electrical PMs" will be covered during Engineering Department new associate training. g. A member of the Engineering Department participates in the hospital-wide Daily Safety Huddles so that any issues which impact patient safety are able to be quickly escalated to the hospital leadership team for resolution.	04/01/16 and ongoing Current and ongoing
	4	Corrective actions will be monitored as follows:	
		a. TCU ground fault receptacles, electrical panels, and outlets in corridors and support spaces serving patient rooms, will be entered into the preventive maintenance (PM) system for tracking and monitoring. The PM system will issue an automatic work order every 6 months to ensure that ground fault receptacles are working properly, that the electrical room remains secure with nothing in front of the electrical panels, and that outlet integrity has been maintained.  b. Inspections will be performed to determine compliance with maintaining electrical wiring and equipment per policy.	Add to PM system by 03/31/16 Inspections to start 04/01/15

Summary Statement of Deficiencies	Tag	Plan of Correction	Completion Date
Summary Statement of Deficiencies	K147	c. Inspections will be done on a monthly basis, and will continue until substantial compliance has been achieved for 3 consecutive months. Inspections will then be done on a quarterly basis for 2 consecutive quarters, and on a random basis thereafter.  d. Inspections are performed by the Plant Manager or designee, and any noted deficiencies are addressed by the Plant Manager with applicable Engineering staff immediately.  e. Plant Manager/designee inspection results and actions taken in response to results are aggregated, analyzed, and trended at the Transitional Care Unit quality meetings.  f. Overall results are reported to the hospital-wide Environment of Care Committee and Quality/Safety Committee on a monthly basis, and will be forwarded to the Board of Trustees every other month until the inspections are completed.	